Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

STATINTL	To : Date: January 19, 1962
	Subject: Current Configurations of Pressure Suit and Parachute
1	The results of the meeting on January 16 thru 18 with regard to changes in
	the pressure suit and parachute are as follows:
	Regarding the pressure suit
	1. A difference was noted between the wrist rings on suit
STATINTL	as compared to The flange type of connections on
STATINTL	wrist rings may be causing a slight amount of trouble
	when reaching for the seat ejection ring. We would like to see this
	flat in the same manner as on suit. Further, this total ring
	assembly should be made smaller if at all possible.
	2. The neck ring on the newer helmets is 1/2 inch bigger in diameter.
	This is a very critical area because of interference with parachute
	harness and shoulder harness straps at this point. We would like to
	see this neck ring go back to its original diameter such as on
STATINTL	suit and helmet.
	3. The helmet cable hold-down fitting is presently plastered on the out-
	side of the neck ring. This again adds another 1/4 of an inch to the
	overall neck ring width just where it is important to be narrow. It
	appears that this fitting can be made to bolt on the bottom of the ring
	and thus have no extension beyond the basic diameter of the ring itself.
STATINTL	4. On suit the neck ring does not match the lower side of

STATINTL

-2- January 19, 1962

the helmet ring when he has his head in a normal attitude prior to locking in place. As a result there is some constant strain on the neck when the helmet is locked up. This fit should be watched when the suit is made.

5. Helmet pressure taps stick out too far and are in a vulnerable position. Propose screwing tap in only when in use. Seal threaded holes with screws for flight.

With regard to the parachute pack and harness, the following configurations were established.

- 1. The connection for the drogue harness must be moved back and outboard so that the drogue fitting always clears the helmet. It has been established that it is to be located on an added outside harness webbing 1-5/8" forward of the top backpan webbing.
- 2. The current basic configuration of the parachute pack, oxygen pan, and the timer case are to remain unchanged. The pack is to have an overall maximum thickness of 6-3/8". We can permit no deviation to a thicker pack. Also see item 14. OK with 19" paracha
- 3. Rocket-Jet disconnects are to be used in place of the Capewells.

January 19, 1962

- 5. The covering on the oxygen and timer pans is to be made or eliminated so that there is no lost space due to fabric or connection problems. Probably the best way to do this is to eliminate the cloth covering entirely over the center of the pans but to fasten it along the edge so that it can carry tension when the pack is pulled up tight.
- 6. The hooks on the elastic bands are to be directly connected to the metal pans. Holes in the pans are probably sufficient.
- 7. The drogue riser configuration is to be such that the apex occurs at the base of the drogue chute itself. The fitting at that point must be strengthened to take the drogue chute loads, probably by means of the tube over the bolt. There are to be two spreaders sewed between the drogue risers to prevent excessive slippage.
- 8. The T-10 risers are also to have a spreader between them in order to back up an inadvertent Rocket-Jet release.
- 9. As a result of these changes, a new harness is required that will permit higher loads to go down the pack webbing. This also means that a non-slip type of adjustment buckle is required on the side adjustment webbing.
- 10. The release and webbing are to be designed for 6000 lb. limit load as applied by the drogue chute. These loads are to be checked at El Centro on the new harness.

-4-

January 19, 1962

- 11. With regard to the drogue chute release
 - a. The inner links are to be machined away per the enclosed drawing.
 - b. The center roller is to have conical ends.
 - c. The release pin is to have a thick shoulder so that the side roller is always positioned to alleviate a hang up.
 - d. All working parts are to be lubricated with solid film lube such as Lubri-Plate or Electrofilm.
 - e. A stop pin is to be incorporated on the inboard link such that there is always at least 3° of over center action available in the linkage.
 - f. The small radius is to be incorporated in the solid guide tube for the flexible cable.
 - g. At conclusion of these tests a more reliable release will be designed and incorporated at a future date.
- 12. The seat kit is to stay exactly as it is with no changes except for the addition of the solid parachute block at the rear end. The drawing of this block is included with this letter.
- 13. A flap is to be incorporated on the bottom of the parachute pack which may be clipped to the seat pack to prevent the possible jamming of parachute risers between the seat pack and the man.
- 14. The maximum permissable pull for an automatic actuation of the timers
 is about 10 lbs. A set of current production timers will be sent to
 Firewel on January 19 for Mockup purposes and to make the detail
 changes required to stay below this maximum force of 10 lbs.

Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

	<u>Approved For Release 2003/04/17</u> : CIA-RDP75B00285R000400080001-9
STATINTL	

-5-

January 19, 1962

15. Flap approx. 6" long is to be sewn to the lower edge of the left wing flap. This is to snap back on the wing flap to enclose the vent hose and communications cord.

- 16. The tab for securing the emergency oxygen cable housing is to be moved aft 3/4".
- 17. The inertia reel shoulder harness buckles must be positioned behind the neck ring to eliminate the possibility of hang up on seat separation.

As a result of the above requirements, the test and parachute schedules will be as follows:

The seven current parachute harnesses now at El Centro will be modified to locate the drogue release in the correct position. The dummy
drops are then to continue using these modified packs at El Centro on
January 22.

STATINTL

- 2. is to make up two new harnesses and packs to the strength required to accept the relocated drogue chute loads. One of these packs is to be available for cockpit checkout on February 2. They will then be used at El Centro for drop tower strength tests.
- 3. The production timers are still being held up at pending the completion of drop tests to varify that the present altitude settings are correct.

	Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9					
STATINTL	-6- January 19, 1962					
	4. Production timers are now undergoing qualification tests at Wright					
	Field. An end target date is February 12.					
	I felt that this meeting was necessary and very productive. The primary					
	issue is the positioning of the drogue chute releases on the harness to elimi-					
	nate any possibility of helmet interference of ejection. This was resolved					
	to everyone's satisfaction.					
	Sincerely, STATIN	1TL				
	EFM/kb					
STATINTL	cc:					

Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

STATINTL	To	: Date: January 19, 1962
	Subj	ect: Current Configurations of Pressure Suit and Parachute
	The	results of the meeting on January 16 thru 18 with regard to changes in
	the p	pressure suit and parachute are as follows:
	Rega	STATINT
	1	. A difference was noted between the wrist rings on suit
STATINTL		as compared to The flange type of connections on
STATINTL		wrist rings may be causing a slight amount of trouble
		when reaching for the seat ejection ring. We would like to see this
		flat in the same manner as on suit. Further, this total ring
		assembly should be made smaller if at all possible. STATINT
	2	. The neck ring on the newer helmets is 1/2 inch bigger in diameter.
		This is a very critical area because of interference with parachute STATINT
		harness and shoulder harness straps at this point. We would like to
		see this neck ring go back to its original diameter such as on
STATINTL		suit and helmet.
	3.	. The helmet cable hold-down fitting is presently plastered on the out-
	J.	side of the neck ring. This again adds another 1/4 of an inch to the
		overall neck ring width just where it is important to be narrow. It
		appears that this fitting can be made to bolt on the bottom of the ring
		and thus have no extension beyond the basic diameter of the ring itself.
STATINTL	4.	on suit the neck ring does not match the lower side of

-2-

January 19, 1962

the helmet ring when he has his head in a normal attitude prior to locking in place. As a result there is some constant strain on the neck when the helmet is locked up. This fit should be watched when the suit is made.

5. Helmet pressure taps stick out too far and are in a vulnerable position. Propose screwing tap in only when in use. Seal threaded holes with screws for flight.

With regard to the parachute pack and harness, the following configurations were established.


- 1. The connection for the drogue harness must be moved back and outboard so that the drogue fitting always clears the helmet. It has been established that it is to be located on an added outside harness webbing 1-5/8" forward of the top backpan webbing.
- 2. The current basic configuration of the parachute pack, oxygen pan, and the timer case are to remain unchanged. The pack is to have an overall maximum thickness of 6-3/8". We can permit no deviation to a thicker pack. Also see item 14.
- 3. Rocket-Jet disconnects are to be used in place of the Capewells.
- 4. The protector flap on the drogue pack is to be reversed thus making the folded end up.

-3-

January 19, 1962

- 5. The covering on the oxygen and timer pans is to be made or eliminated so that there is no lost space due to fabric or connection problems. Probably the best way to do this is to eliminate the cloth covering entirely over the center of the pans but to fasten it along the edge so that it can carry tension when the pack is pulled up tight.
- 6. The hooks on the elastic bands are to be directly connected to the metal pans. Holes in the pans are probably sufficient.
- 7. The drogue riser configuration is to be such that the apex occurs at the base of the drogue chute itself. The fitting at that point must be strengthened to take the drogue chute loads, probably by means of the tube over the bolt. There are to be two spreaders sewed between the drogue risers to prevent excessive slippage.
- 8. The T-10 risers are also to have a spreader between them in order to back up an inadvertent Rocket-Jet release.
- 9. As a result of these changes, a new harness is required that will permit higher loads to go down the pack webbing. This also means that a non-slip type of adjustment buckle is required on the side adjustment webbing.
- 10. The release and webbing are to be designed for 6000 lb. limit load as applied by the drogue chute. These loads are to be checked at El Centro on the new harness.

	Approved For Release 2	Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9				
STATINTL		-6-	January 19,	1962		
		are now undergoing quaget date is February 12.		Wright		
	I felt that this meeting was necessary and very productive. The primary					
	issue is the positioning of the drogue chute releases on the harness to elimi-					
	nate any possibility of helmet interference of ejection. This was resolved					
	to everyone's satisfaction					
		Sincerely,		STATINTL		
	EFM/kb					
STATINTL	cc:					



1-11-62 Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9
THE PROBLEM:

FIRST STAGE SUSPENSION

FITTINGS EXERT PRESSURE ON NECK

RING IMMOBILITING THE HEAD

AND SUBJECTING NECK TO STRESS.



CIA-RDP75B00285R000400080001-9 003/04/17 : CIA-RDP76B00285R000400080001-9






STAT

Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

FIRST STAGE JUSTENSION FITTINGS:

STOWAGE OF FITTINGS UNDERNEATH

NACK RING




Approved For Release 2003/04/17 CIA PDP76B00265R00040006000 STAT ADP7500285R000400080001-9

- a) NECK SPREADER COLLAR ADDED
 - 4) FIRST STAGE FITTINGS MOVED AFT 1/2 INCHES AND OUTBOARD ON SEPARATE SUSPENSION WEB


COMMENTS &

OBJECTIONIABLE NECK PRESSURE
AND MOBILITY PROBLEMS IN SEAT





Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9




STAT STAT STAT STAT STAT



Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9
UN COMFOR TABLE NECK PRESSURE

STAT

STAT



Approved For Release 2003/04/17

STAT

1-17-62

Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9 PRESSURIZED

Coperior For Release 2003/04/17 ; CIA-RD 75800285R0004000

STAT STAT /- 17-62-Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9 PRE SSURIZED

Approved For Release 2003/04/11 - OB-RDP75B00285R0004000 0 001-9

STAT STAT 1-17-62

Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9

RESTRICTED MOBILITY

//04/17 : CIA-POP75B00285R000400080 STAT Approved For Release 2003/04/17 : CIA-RDP75 3028580

Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9
STAT

ed For Release 2003/04/17:CIA-RDP75B00285R000400080001-9


1-17-62

a) FIRST STAGE FITTINGS MOVED AFT 1/2 AND OUTBOARD ON SEPARATE SUSPENSION WEBS.

COMMENTS:

- a) IMPROVED MOBILITY IN SEAT OVER NECK SPREADER COLLAR
 - 4) FIRST STAGE SUSPENSION FITTINGS ALTHOUGH IMPROVED STILL INTER FERE WITH HELMET & NECK RING

proved For Refease 2003/04/17 : CIA EDP75B00285R000400080001-9 STAT







1-17-62 HELME TAPPROVED FOR Release 2003/04/17 SCIA-RDP75B00285R000400080001-9



/- /7-6 ZApproved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9


CONSIDERED MOVING ROTATING FIRST STAGE FITTINGS 90° TO CLEAR NECK RING AND HELMET



WITHOUT SUIT - NECK SPREADER CONLAP


a) KIT WEIGHTED 40#

2) SUSPENSION 1ST STAGE



STATINTLE OMMENTS BY

- a) COMPLAINS ABOUT MEET PRESSURE-CONSIDERS HIGH
- 6) CONSIDERS GROIN COMFORT OK
- C) SUSPENSION LINE THRU C.G. APPEARS OK. FOR COMFORT



RDP75B00285R0 0400 2000



STATINTL

Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

STATINTL

SAME RIG AS


COMMENTS:


a) CLEARS HELMET OK

L) COMPLAINS ABOUT COMFORT

C) PRESSURE FROM MECK COLLAR

AT LEGS AND NECK











SA ANTON OF THE CONVENTIONAL HELMET

2. CLEARANCE OK., NO OBVIOUS PROBLEMS






d For Release 20 0285R000499080001-9 4. 1.

STAT


Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9


- a) SUIT AND NECK-SPREADER COLLAR
- A) SUSPENSION AFT POSITION




COMEMENTS:

- a) CONSIDERS SUSPENSION ACCEPTABLE
- 6) LEG AND GROIN OR
- e) NO NECK PRESSURES
- d) CHEST PRESSURES APPEAR OBVIOUS FROM MANNER OF SUSPENSION










Approved For Release 2003/04/17; **CIA-RDP75B00285R000400080001-9





.....

Approved For Release 2003/04/17,: CIA-RDP75B09285R000400080001-9

- POINT I FIW'D
- 4) THE NECK COLLAR PLACED OUTSIDE.

COMMENTS:


- a) FEELS MORE COMFORTABLE THAN \$4
- 4) CHEST PRESSURES LIGHTER THAN #4
 - e) NO NECK PRESSURES














STATINTL 1-18-62

Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

INI RIG WITHOUT

NECK COLLAR SPREADER IN FINID 1ST STACE.

SUSPENSION POINT.

COMMENTS:

a) COMFORT BETTER THAN #5

L) SEEMS GOOD - NO CRITISMS.





03/04/17 CIA-ROP75B00285R000400080001-9

STAT

400

1. SAME RIG AS #6

2. SUSPENSION IST STAGE IN AFT POSITION

SOSPENSION POINT CHOTE

COMMENTS:

a) NO OBJECTION ABLE CHEST PRESSURE

b) . LEG

C) .. NECK



r Release 2003/04/17 : CIA-R B002855 Relea

STAT STAT STAT

STATINTL

Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

#8

1. RIE WITHOUT NECK SPREADER COLLAR
2. SUSPENSION POINT SAME RS #7

STATINTL

COMMENTS:

a) I LIKE THIS ONE. BEST ONE

SO FAR."









STATINTE- 18-62 Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

1. SAME AS #8
2. SHOWS SLIPPAGE AFTER
SEVERAL JUMPS





STAT STAT



STATINTL


COMMENTS!

a) FEELS ABOUT SAME AS #8



285R000400080001-STAT STAT STAT





1003 14/17 : CIA-RE 77 STAT STAT

SAME RIG AS # 10

a) COLLAR OUTSIDE NECK RING.

COMMENTS:

- a) STILL UNCOMFORTABLE
- 21 DEFINITELY UNDESIRABLE





Approved For Release 2003/04/17 . CIA-REF75B00285R600400060001-9

STATINTL 1-18-62

Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

a) SAME RIG AS NO, 10.
b) SAME SUSPENSION POINTS

B) REMOVED NECK COLLAR

COMMENTS!

STATINTL

a) CONSIDERS MOBILITY BETTER

WITH COLLAR REMOVED - EVEN BETTER

THAN OTHER BIG IN #9 \$ #8

STATINTL

b) LIKES SUSPENSION BETTER

THAN #9


STATINTL

CONSIDERS 17 6000

Approved For Release 2003/04/17 : CIA-ROP75B00285R800

STAT STAT Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

- a) SAME RIG AS #11
- B) SUSPENSION POINT IN AFT
 POSITION



STATINTL

COMMENTS:

a) CONSIDERS MORE COMFORT ABLE IN

CHEST

2) MORE COMFORTABLE ALL AROUND

THIS IS RIG THAT WAS CONSIDERED ACCEPTABLE AND REVISIONS ARE BEING MADE TO THIS CONFIGURATION.

STAT STAT STAT





\$12 1-18-62

MOBIL/7 Approved For Release 2003/09/17; CIA-RDP75B00285R000400080001-9

a) MOBILITY IMPROVED BUT STICK-MORE IMPOVEMENT DESIRED

Approved For Release 2003/04/17 : CIA-RDP75B002B5R0004D0080001-9 Approved For Release 2003/04/17 ; CIA-RDP75B00285R00840008000

1-18-67
MOBI Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9
PRESSURITED

a) PREFERS TO BE PRESSURIZED - REMOVES
HARD SPOTS

Approved Pol Release 2008/0417 20 RDP75B00285R000400080001-9

STAT STAT

- a) HEAD MOBILITY JUST A. LITTLE BETTER - VERY LITTLE DIFFERENCE
- 4 PRESSURITED ARM MOBILITY

 REDUCED BUT NOT CRITICAL

 HAS DIFFICULTY SEEING DOWN

 AND FROM SIDE TO SIDE UNDER

 PRESSURE
- C) WITH HELMET STRAP PULLED DOWN MOBILITY IMPROVED



13 A

Approved For Release 2003/04/17 : CIA-RDP75B00285R000400080001-9

UNPRESSURIZED

14

Approved For Release 2003/04/17: CIA-RDP75B00285R000400080001-9

KIT & CHUTE REPRESENTATIVE

OF FINAL CONFIGURATION